Monday, 11/13/2006 12:40:09 PM

Chantal Lavoie

Process Sheet

omer

: CU-DAR001 Dart Helicopters Services

Drawing Name

: SUPPORT BRACKET

o Number

: 29436

stimate Number

: 10260

P.O. Number This Issue

11/13/2006

S.O. No. : NO

Prsht Rev. First Issue

: N/A : 29435 **Previous Run**

Written By

Checked & Approved By

Comment

Type

MACHINED PARTS

Added inspection level 8

Part Number

: D23623

Drawing Number

D2362 REV E1

Project Number Drawing Revision

: N/A

Material **Due Date**

: NA : 11/20/2006

Qty:

8 Um:

Each

Additional Product

Job Number:



: Est: G 00.05.18

Seq. #:

Machine Or Operation:

Description:

1.0 D2265

Step Support Casting





Comment: Qty.:

Qty Part Number

D2265

1.0000 Each(s)/Unit Step Support

Total:

Description Step Support

2.0

HAAS1

Pick:

Comment: Machine per folio D2362-3

3.0

INSPECT PARTS AS THEY COME OFF MACHINE

HAAS CNC VERTICAL MACHINING #1



Comment: Inspect Level 2

4.0

QC8

SECOND CHECK



Comment: SECOND CHECK



5.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr



Er 06/11/13 x8

84

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
.•									
Part No):	PAR #: Fault Category: N	CR: Yes	No DQ	A:	Date:			

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C C	losed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Ammrayal	Ammroyal			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector			
	,										
				ı							
				4	·						
								*			
0	*	·	*								

NOTE: Date & initial all entries

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SUPPORT BRACKET

Part Number: D23623

Job Number: 29436

Job Number:

Seq. #:

Machine Or Operation:

Description:

6.0

POWDER COATING

POWDER COATING

Comment: POWDER COATING

Powder Coat Gloss White (Ref 4.3.5.1)as per Dart QSI 005 4.3

7.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERS



Comment: INSPECT POWDER COAT

Rubber Cushion



8.0

D23971





Comment: Qty.:

1.0000 Each(s)/Unit Total:

8.0000 Each(s)

Rubber Cushion

Pick:

Qty Part number

Description Rubber

9.0

D23973



Comment: Qty.:

D2397-1

1.0000 Each(s)/Unit Total:

8.0000 Each(s)

Rubber Cushion

Pick:

Qty Part number

Description

Batch

Rubber

B 29 446

10.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



D2397-3

Comment: SMALL & MEDIUM FAB RESOURCE 1

Bond rubber D2397-1 followed by D2397-3 using contact cement

as per Dwg D2362

Batch M 100374



11.0

QC5

INSPECT-WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

12.0

PACKAGING 1

PACKAGING RESOURCE #1





Comment: PACKAGING RESOURCE #1

Identify and Stock Location:



Dart Aerospaee Ltd

	WORK ORDER CHANGES								
STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
						·			
	STEP	·				STEP PROCEDURE CHANGE By Date Qty Chief Eng /			

Part No:	PAR #:	_ Fault Category:	NCR: Yes No DQA:	_ Date: <u>& / (2 / 13</u>
			QA: N/C Closed:	Date:

NCR: WORK ORDER NON-CONFORMANCE (NCR)								
DATE	OTED	Description of NC		Corrective Action Section B	Verification	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
B1205	6.0	Poncler count is missing on the inside of the part. then an ever, and a hard spot to get point into.	12.12	Touch-up insects of the ports using white I mran provid. Apply in nice even conts.	21272		06.12.12	1
		to get point into.			Wir	a:12.11	000	10012.05
							,	

NOTE: Date & initial all entries

Monday, 11/13/2006 12:40:09 PM Chantal Lavoie

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SUPPORT BRACKET

Job Number: 29436

Part Number: D23623

Job Number:



Seq. #:

Machine Or Operation:

Description:

13.0

QC21



Comment: FINAL INSPECTION/W/O RELEASE

FINAL INSPECTION/W/O RELEASE



Job Completion



U 66.12.13

DART AEROSPACE LTD	 Work Order:	25436
	₩,	
Description: Samor Washet	Part Number:	D0360-3
0 0440		
Inspection Dwg: 1) 136 , Rev: C		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Rejest	Method of Inspection	Comments
1.28	20030	1.275	_			
1,200	20010	1.210				
1,000	20010	1,010		,		
080	£0030	0.77			7.50	
0.77	20030	0791				
3.074	20010	3.064				
0.34	20030	0.328			Ŧ -	
1.200	±0.00	1.494				
\$ 0.257	+0.00S	0.257				
1.00	Z8030	2992	5		4.0	
1.88	20.030	0.988				,
0.957	±0010	6.260				-
0.4	20030	0.758				
		·				·
					·	:
-						
	10					:.
		-				
						•
				·		
		- A				

Measured by:	Audited by: JL	Prototype Approval:	W.
Date: oblule	Date: 06/11 13	Date:	t d

Rev	Date	Change	,	Revised by	Approved
A		New Issue		KJ/JLM	